kreor

| | technics | W | Name | Reference | voltage | LxWxH |
|---|--------------|---|---|----------------------------------|------------------------------------|--------------------------|
| | | | Cana 40 main profile gear incl. | KR75520x | | Lx54x80 |
| | | L | Module 40 single | KR93400(5)x-xxxx-xx | 230V | 48x48x55 |
| | | | Module 40 twin | KR93450(5)x-xxxx-xx | 230V | 103x48x55 |
| | | | Module 40 double | KR93475x-xxxx-xx | 230V | 95x48x55 |
| | | H | Holon 40 dir. single | KR93430x-xxxx-xx | 230V | 48x145x100 |
| | | | ligna 40 | KR934900-xxxx-xx | 230V | Lx48x26 |
| | | H | | | | |
| 1 | installation | | | | | |
| | | | | | | |
| | | | | _ | | |
| | | v | | | | / |
| | | X | | | |]} d |
| | | | | | ▶ © ⊕ | ₹ |
| | | // | | ~ | 1 404 | # |
| | | Please make sure that | | ~ | | |
| | | main voltage is disconnected before proceeding! | | ~- | → ⊕ o | |
| | | | before removing the brackets, make sure there is no plaste | er residue left | | |
| 2 | installation | To install the plasterkit, see installation manual KR8050002138. | between the bracket and the plasterkit profile, use stanley | knife to remove Unscrew the sh | neet metal brackets. Keep the M4 | |
| | | supply power at the correct position, see orderform! | the residue if necessary. Do not damage the paint in the pr | rocess! profile to the pl | lasterkit. Do not unscrew the mid | dle screw! |
| | | | | | | |
| | | | | | | |
| | | | | | | / |
| | | | | | | |
| | | | | | | Ţ |
| | | | | \[| 1 | |
| | | | | \[\] | | |
| | | * | * | | ₩₽ | |
| 3 | installation | open the connector tray before installing the main profile | remove female connector from connector tray | | profile inside the plasterkit | |
| | motanation | | | check orderfor | rm for orientation. Nr.1 indicates | s left side on orderform |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| 4 | installation | make sure the cable goes through the square opening inside the main | In case of several pieces, connect the profiles with the cor | | s whith the long bracket and the | nuts |
| | staliation | profile before proceeding | brackets. Slide the brackets into the profile and on top in t | the slotted holes | | |

kreon

