


kreon


kreon nv



kreon









tighten screws on both sides of the profile until the profile is locked in place


fix flanges of plasterkit to plasterboard with screws



fill around perimeter of plasterkit using suitable filler and plaster to hide screws and plasterkit



minimum filler distance, spread out to zero



remove spacer when plaster is dry by pushing it inwards